

-
- WAC 296-104-050, updated the API-510 to the ninth edition.
 - WAC 296-104-100, reworded when power boilers need to be inspected for clarity.
 - WAC 296-104-155(6), removed “in inspected” from the last sentence.
 - WAC 296-104-700, increased the Certificate of inspection fee to \$20.70.